

SAFETY PROTOCOL: Fe-55

Use of radioactive materials requires a safety protocol be submitted to the UNL Radiation Safety Committee (RSC) for approval. This is a safety protocol. To obtain RSC approval:

- Submit an Authorization for Radioactive Material Use request for approval by the UNL RSC. Contact the UNL Radiation Safety Officer (RSO) for specific instructions.
- Agree to use this safety protocol or submit an alternative and equivalent procedure that you develop to meet your unique needs.

All radiation workers must be at least 18 years of age and have completed required radiation safety training. ***Never handle radioactive material prior to the completion of radiation safety training.***

All research protocols involving the radioactive material must be approved by the RSC.

Physical Data

- Half-life of F-55 = 2.7 years.
- Electrons and bremsstrahlung are the primary radiation hazards.
- Maximum electron range in air = 0.6 cm.

Radiation Protection Procedures

1. Special equipment or procedures
 - Use transfer pipettes, spill trays, and absorbent coverings to confine contamination.
 - Volatile chemical forms should be handled in a certified fume hood.
 - Use lab coats, safety glasses, and disposable gloves.
 - Replace gloves as needed.
 - Regularly monitor and promptly decontaminate gloves and work surfaces to maintain contamination and exposures As Low As Reasonably Achievable (ALARA).
 - Select gloves appropriate for chemicals handled.
2. Shielding requirements
 - None is needed with typical research quantities.

3. Surface contamination survey schedule
 - A removable contamination (wipe) survey is the only way to monitor Fe-55 contamination. A survey meter cannot measure Fe-55 contamination.
 - A removable contamination (swipe) survey utilizing a smear and appropriate counter must be performed each month in which radioactive material is used (including sewer disposal). The RSC may require a higher contamination survey frequency depending on the amount of material in process.
 - The action limit for cleanup of removable contamination is 1000 dpm/100 cm². Any indication above this limit on a swipe survey or above two times background with a survey instrument is considered to be contamination. Any accessible area found to be contaminated above this limit shall be decontaminated.
4. Bioassay requirements
 - None routinely required.
5. Dosimetry
 - Typical research quantities of Fe-55 do not present a significant external exposure hazard since the low-energy electrons emitted can hardly penetrate the outer dead layer of the skin.
 - The lower large intestine is the critical organ for ingestion of iron compounds. The spleen and the lungs are the critical organs for inhalation of soluble and insoluble iron compounds, respectively. One or two percent of an uptake of iron is eliminated via urine during the first 24 hours.
 - The annual limit of intake through ingestion is 9.0 mCi.

Waste Disposal

EHS procedures for disposal of hazardous and/or radioactive wastes are to be followed. Fe-55 waste should be segregated from other radioactive waste.

Survey Meters

A survey meter is not required to work with Fe-55.

Personnel Monitoring

Whole body and ring dosimeters are not required for work with Fe-55 at typical research quantities.